

Crochets

L = largeur sangle en mm
R = rupture danN/kg

A = longueur totale (mm)
B = largeur totale (mm)
C = ouverture (mm)
D = épaisseur (mm)
P = poids (g)



L 75
R 7 500
A 95
B 94
C 29/18
D 5
P 470

Référence : 1021



L 75
R 12 000
A 106
B 132
C 32/15
D 15
P 615

Référence : 1067



L 75
R 10 000
A 70
B 116
C 29/15
D 15
P 410

Référence : 1069



L 50
R 5 000
A 69
B 82
C 23
D 12
P 235

Référence : 1070



L 50
R 5 000
A 85
B 74
C 30/15
D 12
P 285

Référence : 1006



L 50
R 5 000
A 59
B 78
C 23/15
D 12
P 195

Référence : 1065



L 50
R 4 500
A 160
B 75
C 24
D 6
P 332

Référence : 1209



L 50
R 4 000
A 129
B 81
C 33/18
D 15
P 410

Référence : 1014 / 50



L 50
R 5 000
A 160
B 84
C 21
D 15
P 490

Référence : 1075



L 50
R 3 000
A 51
B 65
C 28/15
D 3
P 125

Référence : 1012



L 50
R 4 500
A 155
B 71
C 26
D 6
P 325

Référence : 1210



L 50
R 3 000
A 90
B 70
C 36/16
D 9
P 185

Référence : 1007



L 50
R 1 350
A 40
B 72
C 18/10
D 10
P 145

Référence : 1063



L 45
R 750
A 68
B 64
C 27/22
D 7
P 85

Référence : 1005



L 45
R 2 500
A 111
B 62
C 21
D 4
P 150

Référence : 1204



L 45
R 2 500
A 134
B 62
C 23
D 4
P 160

Référence : 1207



L 35
R 3 000
A 91
B 55
C 27/15
D 9
P 165

Référence : 1004



L 35
R 2 500
A 52
B 58
C 17/10
D 9.5
P 111

Référence : 1066



L 35
R 2 000
A 116
B 63
C 23/15
D 12
P 225

Référence : 1014 / 35



L 25
R 1 500
A 56
B 38
C 27/18
D 7
P 65

Référence : 1002



L 25
R 1 500
A 95
B 40
C 13
D 4
P 100

Référence : 1201



L 25
R 500
A 119
B 55
C 28
D 10
P 145

Référence : 1202



L 25
R 500
A 30
B 40
C 8
D 2.5
P 20

Référence : 1213



L 25/35
R 4 000
A 91.40
B 45
C 15
D 12
P 150

Référence : 1017

G-16

S I M A